

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

KO1450
NNW
> 1
1.833 mi.
9680 ft.

VAULT 3675
86TH ST & 21ST AVE
BROOKLYN, NY

NY Spills S104194625
N/A

Site 1 of 2 in cluster KO

Relative:
Higher

Actual:
23 ft.

SPILLS:

Name: VAULT 3675
Address: 86TH ST & 21ST AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9906585 / 1999-11-09
Facility ID: 9906585
Facility Type: ER
DER Facility ID: 100867
Site ID: 115821
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 1999-09-02
Investigator: JHOCONNE
Referred To: Not reported
Reported to Dept: 1999-09-02
CID: 211
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1999-09-02
Spill Record Last Update: 2000-05-23
Spiller Name: CALLER

Spiller Company: CON ED
Spiller Address: 4 IRVING PL
Spiller Company: 001
Contact Name: MARK SCHLAGEL
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL Con ed e2mis notes: approx 1 qt of oil leaking from defective waterbury in V-3675, on 1 yard of dirt. Records show 17ppm. Waterbury was repaired unit was pressured tested, found to be good, 1 sample taken. Chem lab results 99-09195 20 ppm LAZ#04425, Flush dept, reported VS3675 oil clean up completed and removed oil tag. Incident is closed. "

Remarks: "DEFECTIVE VALVE CAUSED 1 QT OF PRODUCT TO SPILL - SAMPLE TAKEN TO CONFIRM 17 PPM PCB - CLEAN UP PENDING RESULTS CON ED 127550"

All Materials:

Site ID: 115821
Operable Unit ID: 1085004
Operable Unit: 01
Material ID: 299308
Material Code: 0541A
Material Name: dielectric fluid
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Units: G
Recovered: .00
Oxygenate: Not reported